
BMP Updates for Jan-May 2022



# Educating Boaters and Enforcing BMPs





- Communication with 31 tenants about BMP violations (1<sup>st</sup> offense)
- 3 of these were repeat violators and received official warnings (2<sup>nd</sup> offense)
- 1 was issued a fee

### Common BMP Violations

- Hydraulic oil washed into water (at least they attempted to recover!)
- Buckets of waste oil sitting out and spilling onto tarps
- Torn tarps, paint particulate, and scraps all over








## More BMP violations!



- Wood shavings and particulate leaving tarp (and getting rained on)
- Spilled paint
- Super sudsy galley water being released









Acceptable sanding








#### Sheens

- 14 significant events reported since January 2022
- 6 for sheens with *unknown* sources
- 6 for sheens with known sources
- 2 for a sunken vessel and a grounded vessel (not BMP related)

## Acknowledging hard work

 Recognizing those who go above and beyond!



# Stormwater and wastewater sampling

	April 2022 Stormwa	ter Sampling Results	
Drainage	% Area	Copper	Zinc
W Sims	5.73%	160.0	41.
E Sims	4.67%	120.0	50.
Vault 1	21.63%	36.1	12.
Vault 2	14.93%	170.0	69.
Vault 3	21.72%	220.0	259.
Vault 4	31.33%	71.0	28.
Area weighted average	100%	118	8
g 170			
Benchmark		147	9

In January, April, May,
October, and November,
stormwater samples are
collected and analyzed for
Cu, Zn, and TSS







### Just a few of the reasons why